



























































# NEW TO RANGE - JUNE 2021

Make	Model	Description	OEM	ETS
 ALFA ROMEO	GIULIETTA (940) (5Y) / 08.13 -->	STABILIZER LINK LR	51805870 50515276 50531823 68259979AA 68201116AA	<b>01.LB.133</b>
 ALFA ROMEO	MITO / 09.08 -->	STABILIZER LINK LR	51805870 50515276 50531823 68259979AA 68201116AA	<b>01.LB.133</b>
 AUDI	A1 (8X1) / 05.10 -->	TRACK CONTROL ARM RH	6R0505224	<b>02.TC.341</b>
 AUDI	A1 (8X1) / 05.10 -->	TRACK CONTROL ARM LH	6R0505223	<b>02.TC.340</b>
 AUDI	A4 (8D2,B5) / 01.95 - 11.00	TRACK CONTROL ARM RH	8E0407506P	<b>02.TC.343</b>
 AUDI	A4 (8D2,B5) / 01.95 - 11.00	TRACK CONTROL ARM LH	8E0407505P	<b>02.TC.342</b>
 AUDI	A4 (8D2,B5) / 01.95 - 11.00	TRACK CONTROL ARM RH	8E0407510P	<b>02.TC.345</b>
 AUDI	A4 (8D2,B5) / 01.95 - 11.00	TRACK CONTROL ARM LH	8E0407509P	<b>02.TC.344</b>
 AUDI	A4 (8E2,B6) / 11.00 - 12.04	TRACK CONTROL ARM LH	8E0407509P	<b>02.TC.344</b>
 AUDI	A4 (8E2,B6) / 11.00 - 12.04	TRACK CONTROL ARM RH	8E0407510P	<b>02.TC.345</b>

	AUDI	A4 (8E2,B6) / 11.00 - 12.04	TRACK CONTROL ARM LH	8E0407505P	<b>02.TC.342</b>
	AUDI	A4 (8E2,B6) / 11.00 - 12.04	TRACK CONTROL ARM RH	8E0407506P	<b>02.TC.343</b>
	AUDI	A4 (8W2, B9) / 05.15-->	STABILIZER LINK REAR LR	8W0505465B	<b>02.LB.658</b>
	AUDI	A5 (F53) / 06.16-->	STABILIZER LINK REAR LR	8W0505465B	<b>02.LB.658</b>
	AUDI	Q5 (FYB) / 05.16-->	STABILIZER LINK REAR LR	8W0505465B	<b>02.LB.658</b>
	AUDI	Q7(4M) / 01.17-->	STABILIZER LINK REAR LR	4M0505465D	<b>02.LB.659</b>
	AUDI	Q7(4M) / 01.17-->	TRACK CONTROL ARM FRONT LR	4M0411317E	<b>02.TC.346</b>
	BMW	1 (F21) xd / 02.12 -->	TRACK CONTROL ARM LH	31156854723 31126854723	<b>03.TC.933</b>
	BMW	1 (F21) xd / 02.12 -->	TRACK CONTROL ARM RH	31126854724 31156854724	<b>03.TC.934</b>
	BMW	2 (F45) / 07.14 -->	AXIAL JOINT LR	32106867404* 32106867405* 32106869424* 32106869425*	<b>03.RE.157</b>
	BMW	3 (F30) xd / 10.11 -->	TRACK CONTROL ARM RH	31126854724 31156854724	<b>03.TC.934</b>
	BMW	3 (F30) xd / 10.11 -->	TRACK CONTROL ARM LH	31156854723 31126854723	<b>03.TC.933</b>

	BMW	3 TOURING (F31) / 10.11 -->	TRACK CONTROL ARM LH	31156854723 31126854723	<b>03.TC.933</b>
	BMW	3 TOURING (F31) / 10.11 -->	TRACK CONTROL ARM RH	31126854724 31156854724	<b>03.TC.934</b>
	BMW	5 (G30) X DRIVE / 11.16-->	STABILIZER LINK REAR LR (PLASTIC)	31306861485	<b>03.LB.280</b>
	BMW	5 (G30) X DRIVE / 11.16-->	STABILIZER LINK REAR LR (METALLIC)	31306861485-M	<b>03.LB.281</b>
	BMW	5 (G30) X DRIVE / 11.16-->	TRACK CONTROL ARM LR	31106861185	<b>03.TC.935</b>
	BMW	5 (G31) X DRIVE / 11.16-->	STABILIZER LINK REAR LR (METALLIC)	31306861485-M	<b>03.LB.281</b>
	BMW	5 (G31) X DRIVE / 11.16-->	STABILIZER LINK REAR LR (PLASTIC)	31306861485	<b>03.LB.280</b>
	BMW	5 (G31) X DRIVE / 11.16-->	TRACK CONTROL ARM LR	31106861185	<b>03.TC.935</b>
	BMW	7 (E32) / 09.86 - 09.94	STABILIZER LINK LEFT	31351139141	<b>03.LB.283</b>
	BMW	7 (E32) / 09.86 - 09.94	STABILIZER LINK RIGHT	31351139142	<b>03.LB.282</b>
	BMW	7 G11 & G12 / 07.15-->	STABILIZER LINK REAR LR (PLASTIC)	31306861485	<b>03.LB.280</b>
	BMW	7 G11 & G12 / 07.15-->	STABILIZER LINK REAR LR (METALLIC)	31306861485-M	<b>03.LB.281</b>

	BMW	8 (G14 CABRIO) / 11.18-->	STABILIZER LINK REAR LR (PLASTIC)	31306861485	<b>03.LB.280</b>
	BMW	8 (G15 COUPE) / 07.18-->	STABILIZER LINK REAR LR (PLASTIC)	31306861485	<b>03.LB.280</b>
	BMW	8 (G16 GRAN COUPE) / 07.19-->	STABILIZER LINK REAR LR (PLASTIC)	31306861485	<b>03.LB.280</b>
	BMW	X1 F48 / 2015/07-->	AXIAL JOINT LR	32106867404* 32106867405* 32106869424* 32106869425*	<b>03.RE.157</b>
	BMW	X1 F49 / 2016/04-->	AXIAL JOINT LR	32106867404* 32106867405* 32106869424* 32106869425*	<b>03.RE.157</b>
	BUICK	RAINIER / 04.01 - 07.12	TRACK CONTROL ARM LH	25786774 RK640294	<b>54.TC.819</b>
	BUICK	RAINIER / 04.01 - 07.12	TRACK CONTROL ARM RH	25786775 RK640293	<b>54.TC.820</b>
	BUICK	REGAL / 01.16-->	STABILIZER LINK REAR LR (METALLIC)	84451421	<b>54.LB.435</b>
	CADILLAC	ATS / 02.13 -->	STABILIZER LINK RIGHT (PLASTIC)	20761142	<b>54.LB.437</b>
	CADILLAC	ATS / 02.13 -->	STABILIZER LINK LEFT (PLASTIC)	20761141	<b>54.LB.436</b>
	CADILLAC	CTS / 09.13 -->	STABILIZER LINK LEFT (PLASTIC)	20761141	<b>54.LB.436</b>
	CADILLAC	CTS / 09.13 -->	STABILIZER LINK RIGHT (PLASTIC)	20761142	<b>54.LB.437</b>

	CHEVROLET	ASTRO / 1985 - 2005	BALL JOINT LR	88911387 9767112	<b>54.BJ.537</b>
	CHEVROLET	BEL AIR / 1955 - 1964	IDLER ARM	3817956 14079325 15596679 3280387	<b>54.IA.116</b>
	CHEVROLET	BLAZER / 01.95 - 12.05	BALL JOINT LR	88911387 9767112	<b>54.BJ.537</b>
	CHEVROLET	CAMARO / 01.16 -->	STABILIZER LINK RIGHT (PLASTIC)	20761142	<b>54.LB.437</b>
	CHEVROLET	CAMARO / 01.16 -->	STABILIZER LINK LEFT (PLASTIC)	20761141	<b>54.LB.436</b>
	CHEVROLET	MALIBU / 01.16-->	STABILIZER LINK REAR LR (METALLIC)	84451421	<b>54.LB.435</b>
	CHEVROLET	MALIBU / 01.16-->	STABILIZER LINK REAR LR (PLASTIC)	23384634	<b>54.LB.434</b>
	CHEVROLET	S10 PICKUP / 01.94-09.05	BALL JOINT LR	88911387 9767112	<b>54.BJ.537</b>
	CHEVROLET	TrailBlazer / 02.01 - 09.12	TRACK CONTROL ARM RH	25786775 RK640293	<b>54.TC.820</b>
	CHEVROLET	TrailBlazer / 02.01 - 09.12	TRACK CONTROL ARM LH	25786774 RK640294	<b>54.TC.819</b>
	CHRYSLER	VOYAGER I (ES) / 08.84 - 09.95	BALL JOINT LR	K04762861AA 4443405 4449553	<b>37.BJ.405</b>
	CHRYSLER	VOYAGER II (GS) / 01.95 - 03.01	BALL JOINT LR	K04762861AA 4443405 4449553	<b>37.BJ.405</b>



CHRYSLER

VOYAGER III (RG) / 02.00 --> BALL JOINT LR

K04762861AA  
4443405  
4449553

**37. BJ. 405**



CITROEN

AX (ZA-) / 07.86 - 12.98 AXIAL JOINT LR

3812A0  
95609129

**04. RE. 704**



CITROEN

C4 PICASSO II / 09.13 --> TRACK CONTROL ARM RH

9678311280  
9807914180\*

**04. TC. 245**



CITROEN

C4 PICASSO II / 09.13 --> TRACK CONTROL ARM LH

9678311380  
9807914280\*

**04. TC. 244**



CITROEN

C5 III / 02.08 --> TRACK CONTROL ARM LR

5178.47

**04. TC. 243**



CITROEN

SAXO / 02.96 - 04.04 AXIAL JOINT LR

3812A0  
95609129

**04. RE. 704**



DAEWOO

MATIZ (KLYA) / 09.98 --> TRACK CONTROL ARM LR

4520075F20  
4705172  
9208987  
9217259  
4520075F21  
4708233  
09208987

**27. TC. 216**



DODGE

CHALLENGER / 1970 - 1974 STABILIZER LINK LR

9785586  
9781049  
530347  
3631686

**06. LB. 446**



FIAT

126 / 01.78 - 01.92 DRAG LINK

4101815

**05. DL. 084**



FIAT

500 / 10.07 --> STABILIZER LINK LR

51801136

**05. LB. 134**


























FIAT

500 / 04.57 - 04.72 DRAG LINK













4101815












**05. DL. 084**













	FIAT	500 L / 01.13 -->	STABILIZER LINK LR	51805870 50515276 50531823 68259979AA 68201116AA	<b>01.LB.133</b>
	FIAT	500 X / 09.14 -->	ENGINE MOUNTING	52004316	<b>05.EM.011</b>
	FIAT	BRAVO II / 04.07 -->	STABILIZER LINK LR	46739116 46549529	<b>05.LB.135</b>
	FIAT	LINEA / 06.07 -->	AXIAL JOINT LR	51784191	<b>05.RE.601</b>
	FIAT	MAREA / 09.96 - 01.02	STABILIZER LINK LR	46739116 46549529	<b>05.LB.135</b>
	FIAT	PANDA / 02.12 -->	BALL JOINT LR	51928536* 51928527* 51905057* 51905058* 51956709* 51956712*	<b>57.BJ.570</b>
	FIAT	PANDA / 02.12 -->	STABILIZER LINK LR	51801136	<b>05.LB.134</b>
	FIAT	PANDA (169) / 09.03 -->	STABILIZER LINK LR	50706957 51856873	<b>05.LB.133</b>
	FORD	C-MAX / 10.03 --> 03.07	TRACK CONTROL ARM FRONT RIGHT	4M513A423AC* 4M513A423BC*	<b>06.TC.531</b>
	FORD	C-MAX / 02.07 -->	TRACK CONTROL ARM FRONT RIGHT	4M513A423AC* 4M513A423BC*	<b>06.TC.531</b>
	FORD	C-MAX / 10.03 --> 03.07	TRACK CONTROL ARM FRONT LEFT	4M513A424AC* 4M513A524AC*	<b>06.TC.530</b>

	FORD	C-MAX / 02.07 -->	TRACK CONTROL ARM FRONT LEFT	4M513A424AC* 4M513A524AC*	<b>06.TC.530</b>
	FORD	COURIER / 01.79-12.82	STABILIZER LINK LR	9785586 9781049 530347 3631686	<b>06.LB.446</b>
	FORD	KA / 02.09 -->	STABILIZER LINK LR	51801136	<b>05.LB.134</b>
	FORD	MONDEO III / 11.00 - 08.07	TRACK CONTROL ARM FRONT LEFT	1311417*	<b>06.TC.528</b>
	FORD	MONDEO III / 11.00 - 08.07	TRACK CONTROL ARM FRONT RIGHT	1311416*	<b>06.TC.529</b>
	FORD	MONDEO IV / 03.07 -->	ENGINE MOUNTING	6Q0199851AQ 6Q0199851AG	<b>31.EM.839</b>
	FORD	S-MAX / 05.06 -->	ENGINE MOUNTING	6Q0199851AQ 6Q0199851AG	<b>31.EM.839</b>
	FORD	TAURUS / 01.96 - 12.07	STABILIZER LINK LH (PLASTIC)	88912265	<b>73.LB.178</b>
	FORD	TAURUS / 01.96 - 12.07	STABILIZER LINK RH (PLASTIC)	88912266	<b>73.LB.179</b>
	GMC	ENVOY / 01.02 - 12.09	TRACK CONTROL ARM RH	25786775 RK640293	<b>54.TC.820</b>
	GMC	ENVOY / 01.02 - 12.09	TRACK CONTROL ARM LH	25786774 RK640294	<b>54.TC.819</b>
	GMC	SAFARI / 1985 - 2005	BALL JOINT LR	88911387 9767112	<b>54.BJ.537</b>



	HYUNDAI	ELANTRA (XD) / 06.00 -->	CROSS ROD	552202F000 552202F0000	<b>09.CR.252</b>
	HYUNDAI	EQUUS / 01.14-->	TRACK CONTROL ARM REAR LR	552703T100 552703M100 RK642357	<b>08.TC.782</b>
	HYUNDAI	GENESIS / 01.08-->	TRACK CONTROL ARM REAR LR	552703T100 552703M100 RK642357	<b>08.TC.782</b>
	HYUNDAI	SOLARIS / 01.2017->	TRACK CONTROL ARM FRONT LEFT LOWER	54500H5000	<b>08.TC.780</b>
	HYUNDAI	SOLARIS / 01.2017->	TRACK CONTROL ARM FRONT RIGHT LOWER	54501H5000	<b>08.TC.781</b>
	ISUZU	ASCENDER / 01.03 - 12.08	TRACK CONTROL ARM LH	25786774 RK640294	<b>54.TC.819</b>
	ISUZU	ASCENDER / 01.03 - 12.08	TRACK CONTROL ARM RH	25786775 RK640293	<b>54.TC.820</b>
	JAGUAR	X-TYPE (CF1) / 06.01 -->	TRACK CONTROL ARM FRONT RIGHT	1311416*	<b>06.TC.529</b>
	JAGUAR	X-TYPE (CF1) / 06.01 -->	TRACK CONTROL ARM FRONT LEFT	1311417*	<b>06.TC.528</b>
	JEEP	CHEROKEE / 01.15 -->	TRACK CONTROL ARM FRONT LEFT	68282329AA K68282329AA	<b>35.TC.690</b>
	JEEP	CHEROKEE / 01.15 -->	TRACK CONTROL ARM FRONT RIGHT	68282328AA K68282328AA	<b>35.TC.691</b>
	JEEP	CHEROKEE (KL) / 11.13 -->	STABILIZER LINK LR	68224731AC 68224731AA 68224731AD	<b>35.LB.531</b>

	JEEP	RENEGADE / 07.14 -->	ENGINE MOUNTING	52004316	<b>05.EM.011</b>
	JEEP	WRANGLER I (YJ) / 08.86 - 08.95	STABILIZER LINK LR	52002609 520026098	<b>35.LB.532</b>
	JEEP	WRANGLER III (JK) / 04.07 -->	DRAG LINK	K52059982AG 52059982AG	<b>35.DL.495</b>
	KIA	CERATO / 03.04 -->	CROSS ROD	552202F000 552202F0000	<b>09.CR.252</b>
	KIA	NIRO / 09.16-->	TRACK CONTROL ARM FRONT R	54501G2100	<b>09.TC.704</b>
	KIA	NIRO / 09.16-->	TRACK CONTROL ARM FRONT L	54500G2100	<b>09.TC.703</b>
	LANCIA	YPSILON (846) / 05.11 -->	BALL JOINT LR	51928536* 51928527* 51905057* 51905058* 51956709* 51956712*	<b>57.BJ.570</b>
	LANCIA	YPSILON (846) / 05.11 -->	STABILIZER LINK LR	51801136	<b>05.LB.134</b>
	LEXUS	RX 330 / 04.01 --> 06.12	TRACK CONTROL ARM REAR LOWER LR	4871048040 487100E010*	<b>29.TC.756</b>
	LEXUS	RX 400h / 01.06 - 12/08	TRACK CONTROL ARM REAR LOWER LR	4871048040 487100E010*	<b>29.TC.756</b>
	MAZDA	626 I (CB) / 05.79 - 10.82	STABILIZER LINK LR	9785586 9781049 530347 3631686	<b>06.LB.446</b>

	MAZDA	B2000 / 01.80 - 06.87	STABILIZER LINK LR	9785586 9781049 530347 3631686	<b>06.LB.446</b>
	MAZDA	RX7 I (SA) / 03.78 - 03.86	STABILIZER LINK LR	9785586 9781049 530347 3631686	<b>06.LB.446</b>
	MERCEDES	C-CLASS (W205) / 12.13 -->	STABILIZER LINK RH	2053231017 A2053231017	<b>15.LB.910</b>
	MERCEDES	C-CLASS (W205) / 12.13 -->	STABILIZER LINK LH	2053230917 A2053230917	<b>15.LB.909</b>
	MERCEDES	E-CLASS (W213) 4x4 / 01.16-->	STABILIZER LINK LH	2053230917 A2053230917	<b>15.LB.909</b>
	MERCEDES	E-CLASS (W213) 4x4 / 01.16-->	STABILIZER LINK RH	2053231017 A2053231017	<b>15.LB.910</b>
	MERCEDES	E-SERISI (W212 ) / 01.09 -->	TIE ROD END LH	2123308100 2183300300	<b>15.TR.528</b>
	MERCEDES	E-SERISI (W212 ) / 01.09 -->	TIE ROD END RH	2123308200 2183300400	<b>15.TR.529</b>
	MERCEDES	G-CLASS (W463) / 01.97 - 12.18	DRAG LINK	4634631115	<b>15.DL.122</b>
	MERCEDES	MK / 12.87 - 09.96	REPAIR KIT	0003500205	<b>15.TS.150</b>
	MERCEDES	NG 1013 - 3850 / 08.73 - 09.96	REPAIR KIT	0003500205	<b>15.TS.150</b>
	MERCEDES	SPRINTER (C910) / 06.18 -->	AXIAL JOINT LR	A9074606300 9074606300	<b>15.RE.496</b>



MERCEDES

SPRINTER (C910) / 06.18 -->

TRACK CONTROL ARM FRONT LEFT LOWER

9103302500

15.TC.477



MERCEDES

SPRINTER (C910) / 06.18 -->

TRACK CONTROL ARM FRONT RIGHT LOWER

9103302600

15.TC.478



MERCEDES

VITO (W447) / 10.14 -->

STABILIZER LINK RIGHT

4473200289

15.LB.908



MERCEDES

VITO (W447) / 10.14 -->

STABILIZER LINK LEFT

4473200189

15.LB.907



RESİM HAZIRLANIYOR  
MITSUBISHI

CANTER 711 / 01.12 -->

AXIAL JOINT LR

ME778318

16.RE.122



MITSUBISHI

COLT VI / 06.04 -->

AXIAL JOINT LR

MR594094\*

16.RE.120



MITSUBISHI

COLT VI / 06.04 -->

STABILIZER LINK LR

MN125838  
4543200110

16.LB.882



MITSUBISHI

SPACE WAGON (N3\_W, N4\_W)  
/ 10.91 - 10.98

AXIAL JOINT LR

MB870078  
MR131857

16.RE.121



NISSAN

ALTIMA / 06.93 - 09.01

BALL JOINT LR

RK620346\*  
545009B000\*  
RK620347\*  
545019B000\*

18.BJ.254



NISSAN

ALTIMA / 01.13 - 01.15

TRACK CONTROL ARM LH

545013TA0B  
545013TA0B

18.TC.628



NISSAN

ALTIMA / 01.13 - 01.15

TRACK CONTROL ARM RH

545003TA0B  
545003TA0B

18.TC.629



NISSAN

MICRA V (K14) / 12.16-->

AXIAL JOINT LR

480015FA6A\*

18.RE.145



OPEL

AGILA (H00) / 09.00 -->

TRACK CONTROL ARM LR

4520075F20  
4705172  
9208987  
9217259  
4520075F21  
4708233  
09208987

**27. TC. 216**



OPEL

CORSA-F [P2JO] / 01.19-->

BALL JOINT

9832039280\*  
9831626480\*

**19. BJ. 159**



OPEL

INSIGNIA B / 01.17-->

STABILIZER LINK REAR LR (PLASTIC)

23384634

**54. LB. 434**



PEUGEOT

106 I / II / 08.91 -->

AXIAL JOINT LR

3812A0  
95609129

**04. RE. 704**



PEUGEOT

106 II (1) / 04.96 -->

AXIAL JOINT LR

3812A0  
95609129

**04. RE. 704**



PEUGEOT

308 II / 09.13 -->

TRACK CONTROL ARM RH

9678311280  
9807914180\*

**04. TC. 245**



PEUGEOT

308 II / 09.13 -->

TRACK CONTROL ARM LH

9678311380  
9807914280\*

**04. TC. 244**



PEUGEOT

407 (6D\_) / 05.04 -->

TRACK CONTROL ARM LR

5178.47

**04. TC. 243**



RENAULT

TWINGO III / 09.14 -->

TIE ROD END LH

485204628R  
4533307100

**22. TR. 936**



RENAULT

TWINGO III / 09.14 -->

TIE ROD END RH

485208910R  
4533307000

**22. TR. 937**















SAAB

9-7X / 01.05 - 12.09

TRACK CONTROL ARM RH

25786775  
RK640293

**54. TC. 820**

	SAAB	9-7X / 01.05 - 12.09	TRACK CONTROL ARM LH	25786774 RK640294	<b>54.TC.819</b>
	SEAT	ARONA (KJ7) / 07.17-->	AXIAL JOINT LR	2Q0423810D	<b>31.RE.638</b>
	SEAT	AROSA (6H) / 05.97 - 06.04	AXIAL JOINT LR	6X0422803A* 6X0422804A*	<b>31.RE.639</b>
	SEAT	CORDOBA III / 10.02 -->	ENGINE MOUNTING	6Q0199851AQ 6Q0199851AG	<b>31.EM.839</b>
	SEAT	EXEO (3R2) / 12.08 -->	TRACK CONTROL ARM RH	8E0407506P	<b>02.TC.343</b>
	SEAT	EXEO (3R2) / 12.08 -->	TRACK CONTROL ARM LH	8E0407505P	<b>02.TC.342</b>
	SEAT	EXEO (3R2) / 12.08 -->	TRACK CONTROL ARM LH	8E0407509P	<b>02.TC.344</b>
	SEAT	EXEO (3R2) / 12.08 -->	TRACK CONTROL ARM RH	8E0407510P	<b>02.TC.345</b>
	SEAT	IBIZA III / 08.99 - 02.02	ENGINE MOUNTING	6Q0199851AQ 6Q0199851AG	<b>31.EM.839</b>
	SEAT	IBIZA V (KJ1) / 01.17-->	AXIAL JOINT LR	2Q0423810D	<b>31.RE.638</b>
	SKODA	FABIA / 12.99 -->	ENGINE MOUNTING	6Q0199851AQ 6Q0199851AG	<b>31.EM.839</b>
	SKODA	FABIA Combi / 10.07 -->	ENGINE MOUNTING	6Q0199851AQ 6Q0199851AG	<b>31.EM.839</b>



SKODA

KAMIQ / 01.20--&gt;

AXIAL JOINT LR

2Q0423810D

**31.RE.638**

SKODA

ROOMSTER / 09.06 --&gt;

ENGINE MOUNTING

6Q0199851AQ  
6Q0199851AG**31.EM.839**

SKODA

SCALA / 06.19--&gt;

AXIAL JOINT LR

2Q0423810D

**31.RE.638**

SKODA

SUPERB / 02.02 --&gt;

TRACK CONTROL ARM RH

8E0407506P

**02.TC.343**

SKODA

SUPERB / 02.02 --&gt;

TRACK CONTROL ARM LH

8E0407509P

**02.TC.344**

SKODA

SUPERB / 02.02 --&gt;

TRACK CONTROL ARM RH

8E0407510P

**02.TC.345**

SKODA

SUPERB / 02.02 --&gt;

TRACK CONTROL ARM LH

8E0407505P

**02.TC.342**

SMART

FORFOUR / 01.04 --&gt;

STABILIZER LINK LR

MN125838  
4543200110**16.LB.882**

SUBARU

FORESTER (SJ\_) / 03.13 --&gt;

STABILIZER LINK LR

20420XA000

**26.LB.735**

SUBARU

LEVORG / 05.15--&gt;

STABILIZER LINK LR

20420XA000

**26.LB.735**

SUBARU

TRIBECA / 01.05 --&gt;

STABILIZER LINK LEFT











20470XA010  
488300C020**26.LB.736**

SUBARU













TRIBECA / 01.05 --&gt;

STABILIZER LINK RIGHT

20470XA000  
488400C010**26.LB.737**

	SUBARU	TRIBECA / 01.05 -->	STABILIZER LINK LR	20420XA000	<b>26.LB.735</b>
	SUBARU	XV (GP) / 03.12 -->	STABILIZER LINK LR	20420XA000	<b>26.LB.735</b>
	SUZUKI	LIANA (ER) / 07.01 -->	STABILIZER LINK LR	4663059J00	<b>27.LB.431</b>
	SUZUKI	WAGON R+ (EM) / 02.98 - 05.00	TRACK CONTROL ARM LR	4520075F20 4705172 9208987 9217259 4520075F21 4708233 09208987	<b>27.TC.216</b>
	TESLA	MODEL S / 01.12 - 12.16	STABILIZER LINK LR	103060300B	<b>59.LB.304</b>
	TOYOTA	AVENSIS T27 / 2009/01 - -	TRACK CONTROL ARM FRONT RIGHT	4506805080*	<b>29.TC.760</b>
	TOYOTA	AVENSIS T27 / 2009/01 - -	TRACK CONTROL ARM FRONT LEFT	4606905080*	<b>29.TC.759</b>
	TOYOTA	CAMRY (#V10) / 06.91 - 09.97	STABILIZER LINK RUBBER	4881533011 4881533010 4881533030 4881507010	<b>29.SR.114</b>
	TOYOTA	HIGHLANDER / 01.01 - 12.13	TRACK CONTROL ARM REAR LOWER LR	4871048040 487100E010*	<b>29.TC.756</b>
	TOYOTA	HIGHLANDER / 01.08 - 01.13	TRACK CONTROL ARM REAR LOWER LR	4873048160	<b>29.TC.757</b>
	TOYOTA	Land Cruiser 200 (_J2_) 4.7 V8 (UZJ200) / 2008/01 - -	TRACK CONTROL ARM REAR UPPER LH	4871060150	<b>29.CR.504</b>



	TOYOTA	Land Cruiser 200 (_J2_) 4.7 V8 (UZJ200) / 2008/01 - -	TRACK CONTROL ARM REAR UPPER RH	4871060140	<b>29.CR.505</b>
	TOYOTA	SEQUOIA (_K3_, _K4_) / 09.00 - 10.07	STABILIZER LINK LR	4882034010	<b>29.LB.415</b>
	TOYOTA	TUNDRA Pick-up (_K3_, _K4_) / 02.99 - 11.06	STABILIZER LINK LR	4882034010	<b>29.LB.415</b>
	TOYOTA	VENZA / 11.08-01.15	TRACK CONTROL ARM REAR LOWER LR	4873048160	<b>29.TC.757</b>
	VOLKSWAGEN	FOX / 04.05 -->	ENGINE MOUNTING	6Q0199851AQ 6Q0199851AG	<b>31.EM.839</b>
	VOLKSWAGEN	FOX (5Z1, 5Z3) / 10.03 -->	AXIAL JOINT LR	6X0422803A* 6X0422804A*	<b>31.RE.639</b>
	VOLKSWAGEN	LUPO (6X1,6E1) / 09.98 - 07.05	AXIAL JOINT LR	6X0422803A* 6X0422804A*	<b>31.RE.639</b>
	VOLKSWAGEN	PASSAT V (3B3,3B6) / 11.00 - 05.05	TRACK CONTROL ARM LH	8E0407505P	<b>02.TC.342</b>
	VOLKSWAGEN	PASSAT V (3B3,3B6) / 11.00 - 05.05	TRACK CONTROL ARM RH	8E0407506P	<b>02.TC.343</b>
	VOLKSWAGEN	PASSAT V (3B3,3B6) / 11.00 - 05.05	TRACK CONTROL ARM RH	8E0407510P	<b>02.TC.345</b>
	VOLKSWAGEN	PASSAT V (3B3,3B6) / 11.00 - 05.05	TRACK CONTROL ARM LH	8E0407509P	<b>02.TC.344</b>
	VOLKSWAGEN	POLO (6N1) / 10.94 - 10.99	AXIAL JOINT LR	6X0422803A* 6X0422804A*	<b>31.RE.639</b>



VOLKSWAGEN

POLO (9N\_) / 10.01 - 11.09

ENGINE MOUNTING

6Q0199851AQ  
6Q0199851AG**31.EM.839**

VOLKSWAGEN

POLO (AW1, BZ1) / 06.17--&gt;

AXIAL JOINT LR

2Q0423810D

**31.RE.638**

VOLKSWAGEN

T-CROSS / 02.19--&gt;

AXIAL JOINT LR

2Q0423810D

**31.RE.638**

VOLKSWAGEN

TIGUAN / 09.07 --&gt;

TRACK CONTROL ARM RH

3C0407152E

**31.TC.703**

VOLKSWAGEN

TIGUAN / 09.07 --&gt;

TRACK CONTROL ARM LH

3C0407151E

**31.TC.702**

VOLVO

FH 12: FH 12/420 / 08.1993--&gt;

TRACK CONTROL ARM BUSHING

6889509  
81953020042  
81953020041  
42535204  
274019  
81432206203  
11015964  
273373**05.SB.257**

VOLVO

FH 12: FH 12/460 / 08.1998--&gt;

TRACK CONTROL ARM BUSHING

6889509  
81953020042  
81953020041  
42535204  
274019  
81432206203  
11015964  
273373**05.SB.257****Elbir Oto Yedek Parça imalat ve tic. ltd. Őti.**

Karayolları Mah. 559. Sok. No:14 Küçükköy, 34255 GaziosmanpaŐa - İSTANBUL / TURKEY

T. +90 212 537 3535 pbx F. +90 212 538 0715 E. info@etsauto.com

Copyright ©2015 Elbir Oto